

Erratum

AWS A5.8M/A5.8:2004, *Specification for Filler Metals for Brazing and Braze Welding*

Page 6. In Table 4, titled “Chemical Composition Requirements for Copper, Copper-Zinc, and Copper-Phosphorous Filler Metals,” change the UNS number for BCuP-9 to C55385.