



Errata for AWS D1.1/D1.1M:2004, *Structural Welding Code—Steel*

(updated 7/21/2006 1:25:00 PM)

Page 43 — Figure 2.4 cross reference — incorrect reference — change to “(see 2.8.1.2)”

page 58 — Section 3.5.2 note – incorrect reference to “*ASTM ET 40*” – change to “*ASTM E 140*”

Page 61 — Section 3.13.4 – incorrect reference to 2.36.6.6 and 2.36.6.7 – change to 2.20.6.6 and 2.20.6.7

Page 67 — Table 3.2, Group B – ASTM A 500 Grade C omitted from printed table – add ASTM A 500 Grade C to Table 3.2, Group B

Page 118 — Figure 3.11, Note 2 – incorrect reference to Table 4.8 – change to Table 4.9

Page 194 — Table 5.8, Note 1 – incorrect reference to 3.5.2 – change to “4.7.4”

Page 196 — Figure 5.2, far right sketch – incorrect reference to note 6 – change to note 4

page 309 — Symbol “ β ”, second row – incorrect symbol used, “R” not in italics (i.e., root opening) – change to “*R*” in italics (i.e., outside radius)

Page 393 — C1.4.1(7) – incorrect header – change to “C1.4.1(8) For OEM applications...”

Page 393 — C1.4.1(8) – incorrect header – change to “C1.4.1(7) The Engineer is responsible...”

page 425 — Section C3.13.1 – incorrect reference to Figure 3.3 – change to Figure 3.4