

AWS D10.7M/D10.7:2000, Guide for the Gas Shielded Arc Welding of Aluminum and Aluminum Alloy Pipe

Page 2, 2.1 Safety References, change "NFPA 51B, *Standard for Fire Prevention in Use of Cutting and Welding Processes*" to "NFPA 51B, *Standard for Fire Prevention in Use of Cutting, Welding, and Hot Work Processes*".

Page 4, 4. Aluminum Pipe Alloys and Their Characteristics, fifth paragraph, change "resistance of corrosion" to "resistance to corrosion".

Page 5, Table 2, Note B, change "improved color" to "improve color"

Page 16, 7.4 Inert Gas, change (SG-heA-X) to (SG-HeA-X)

Page 26, 14.5 How To Prevent Fires, change "• Develop adequate ventilation procedures and use proper equipment used to do the job safely." to "• Develop adequate ventilation procedures and use proper equipment to do the job safely."

ERRATA

AWS D10.7M/D10.7:2000, *Guide for the Gas Shielded Arc Welding of Aluminum and Aluminum Alloy Pipe*

Page 23, 11.2 Gas Metal Arc Welding, last sentence, take out word "tungsten".

Page 25, 14.5 How To Prevent Fires, change "10 meters (33 feet)" to "11 meters (35 feet)".