

## Errata

### AWS D17.1-2001 Specification for Fusion Welding for Aerospace Application

Page iii Personnel, add M. Webber Raytheon Co. after J. Waugh Lockheed Martin Aeronautics.

Pg 9 Table 4.3 Revise Footnote (1) to read: A groove weld does not qualify for fillet welds in base metal  $\leq 0.063$  in. in thickness.

Pg.71 Under B3. Procedure Revised to read as follows: Managing Director of Technical Services

EFM June 12, 2001